



NB: Positions of Boreholes and/or Trial Pits are only indicative unless dimensioned

Site: Slindon Pond

STL:J14617

Fig No: 2

Date: 25 November 2020

Silt Depth (Simplified) – all values in metres



Southern Testing: Keeble House, Stuart Way, East Grinstead, West Sussex RH19 4QA
ST Consult: Twigden Barns, Brixworth Road, Creton, Northampton NN6 8NN

